

drvgen - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
20371	Bug	Assigned	Normal	TSI-148 bridge does not support a master window with multiple data transfer modes	John Diamond	07/23/2018 11:07 AM
20402	Bug	Resolved	Normal	Constants generated for bitfields and enums can cause redeclaration	John Diamond	07/23/2018 10:30 AM
20408	Bug	Resolved	Normal	runtime_error in generated getDeviceInSlot() does not include the driver name	John Diamond	07/23/2018 11:27 AM
20432	Bug	Work in progress	Normal	Kernel-level xxxmod_device_get() routine has bbpm250x12 hard-coded	John Diamond	07/24/2018 03:00 PM